



IMPORTANT: VERIFY ALL FAN MOTOR WIRING MATCHES OUTPUT VOLTAGE FROM EDRI (REFER TO THE CONNECTION DIAGRAM)
POWER TO THE FAN MUST BE PROVIDED BY THE EDRI. MOTOR COULD BE DAMAGED IF LINE VOLTAGE
IS APPLIED TO THE FAN DIRECTLY.